Abstract

Piezoceramic multilayer actuators and a process for their manufacture

During operation, large tensile stresses act on the insulating region under the base metallisation with external electrodes on piezoceramic multilayer actuators. Since this insulating region forms a homogeneous unit together with the base metallisation and the interconnecting layer, this fails when the tensile strength of the weakest element is exceeded and cracks develop. The cracks running unchecked through the insulating region are very critical, since they reduce the insulation distance and seriously increase the probability of actuator failure due to flashovers.

According to the invention it is therefore proposed that, in the inactive region (14), the surface (10) of the multilayer actuator (1) has a pattern (18) that is produced by erosions (19) interrupting the surface (10), and that the base metallisation (11) is deposited exclusively on the surface (10) left by the pattern (18).

25 (Figure 3)

20